Message

From: Barnett, Thomas R [Thomas.Barnett@arcelormittal.com]

Sent: 1/26/2017 6:22:57 PM
To: sean.f.fitzgerald@uscg.mil

CC: Beslow, Mike [beslow.mike@epa.gov]; Benoit, Simonne T [Simonne.Benoit@arcelormittal.com]

Subject: slight sheen discharge at 11:25

Attachments: IMG_0318.jpg

Sean, Mike, at 11:25 National noted some white material coming out the 009/010 Outfalls which formed sheen. The episode ended in about ten minutes. We have a strip of rainbow sheen about 6 inches wide by six feet that has built up inside the booms. National is on the scene and is vacuuming up the sheen. A boat is being put into the water to vacuum up any part of this that they cannot reach from the shore.

We have alerted Operational personnel and they are currently evaluating the process to determine if we can find any activity that we can link to this.

We just called it in to the NRC, Incident number 1169567.

Thomas Barnett | Manager, Environmental Technology ArcelorMittal Indiana Harbor LLC. ArcelorMittal USA LLC

Environmental Department | 3001 Dickey Road, Sta. 001 East Chicago, IN 46312

T +219 399 2380 | M +219 313 1605 | F +219 399 3211 | www.arcelormittal.com